

ADEQ

Hazardous Waste Division

Technical Branch

Trip Report

Project	Cedar Chemical Site
Location	Helena-West Helena
Date	4/27/2012
Time	1100 to 1136 hours
Reason	Monthly Site Visit
ADEQ personnel	Annette Cusher Jim Rigg
Facility, contractor and EPA personnel	Mr. Harrington
Activity Summary	<p>Jim and I were met upon arrival at the site by Mr. Harrington. The following issues were discussed during the walk through.</p> <ul style="list-style-type: none"> • A pole was removed cracking the asphalt while demolishing a shed. The remaining poles were cut off at the level of the asphalt. • The old lab building is collecting water after rain events and has become moldy. Harcross would like to demolish the building. • The waste from the renovation of the sump is still covered on a slab. Mr. Harrington indicated Harcross was in contact with Clean Harbors for disposal. • Mr. Harrington also indicated that Harcross would be running underground utilities when they begin to utilize the unused unit. • There are several five gallon buckets of what appears to be purge water (buckets are labeled with monitoring well numbers) still on-site. Harcross would like to know what should be done with the containers. • There is a desk and files being moved into the warehouse. • Harcross is planning on placing fresh gravel in the boneyard and placing the "loose" equipment into the boneyard to improve the look of the site. • There are some empty, damaged containers in a area of the site. Harcross indicated that Enviro Tech has been told to properly dispose if the waste containers.



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:		Cedar Chemical Site						
Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	1	Of	6		Date:	4/27/2012	Time:	
Description:		Cracked asphalt from pole removal						



Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	2	Of	6		Date:	4/27/2012	Time:	
Description:		Area where poles were cut off at asphalt level						



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:		Cedar Chemical Site						
Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	3	Of	6		Date:	4/27/2012	Time:	
Description:		Covered waste pile						



Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	4	Of	6		Date:	4/27/2012	Time:	
Description:		5 gallon containers of purge water						



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:		Cedar Chemical Site						
Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	5	Of	6		Date:	4/27/2012	Time:	
Description:		Close up of 5 gallon container label						



Photographer:		A. Cusher			Witness:		J. Rigg	
Photo #	6	Of	6		Date:	4/27/2012	Time:	
Description:		Damaged empty containers						

